

Job Number	Date In	Registration Number	Job Description	Latest Distance	Workshop Job Sheet Type	Make Model Derivative
00000356	21/12/2017	Section 40	Response Service 2-Type 1	22775	Scheduled Maintenance	SKODA SUPERB ESTATE
			Misc Body			
			Key / Remote			
			Brake Pad			
			Tracking			
			Road Test			
00000496	28/12/2017	Section 40	Low Tread	22775		SKODA SUPERB ESTATE
00001274	14/02/2018	Section 40	clipped central refuge kerb puncturing both offside tyres and denting alloys	25305	Damage	SKODA SUPERB ESTATE
			Damage			
			TPMS Fault			
			Tyre Damage			
			Tracking/ Alignment			
			Road Test			
00001413	15/02/2018	Section 40	Low Tread	25305	Repairs	SKODA SUPERB ESTATE
00002219	11/04/2018	Section 40	Loss of tyre pressure over last two days in the R/N/S tyre causing warning light to come on. Nothing obvious seen.	29993	Breakdown	SKODA SUPERB ESTATE
00002368	17/04/2018	Section 40	Puncture	29993	Repairs	SKODA SUPERB ESTATE

00002643	20/04/2018	Section 40	Low Tread	30834	Repairs	SKODA SUPERB ESTATE
			Puncture			
00003023	23/05/2018	Section 40	Type 2 Light Vehicle Inspection-Type 2 Saftey Inspection. Oil & Filter. Fuel Filter.	34587	Scheduled Maintenance	SKODA SUPERB ESTATE
			Replace Both Front Disc's and pads			
			Replace Both Rear Disc's and Pads			
			Top up			
00003510	26/06/2018	Section 40	Run Lock System Softwarre update	36600	Modification	SKODA SUPERB ESTATE
00003524	08/06/2018	Section 40	Puncture	35925	Other	SKODA SUPERB ESTATE
00004066	21/07/2018	Section 40	Puncture	38500	Other	SKODA SUPERB ESTATE
00004211	01/08/2018	Section 40	Low Tread	40689	Other	SKODA SUPERB ESTATE
00005034	26/09/2018	Section 40	Failed Collection vehicle not there	45058	Scheduled Maintenance	SKODA SUPERB ESTATE
			Type 3 light Vehicle Inspection-Type 3 Safety Inspection. Oil & Filter. Air Filter. Pollen Filter.			
			Replace Front Brake Pad			
			Replace Rear Brake Pad			

			Replace Rear N/S Low Tread			
			Add All Top up			
			Replace Front O/S o/s/f fog light inop			
00005268	25/09/2018	Section 40	Tyre Damage Side Wall	46035	Other	SKODA SUPERB ESTATE
00005351	11/10/2018	Section 40	Low Tread	46035	Other	SKODA SUPERB ESTATE
00005587	06/09/2018	Section 40	Wiper Blade	46923	Other	SKODA SUPERB ESTATE
00006070	23/11/2018	Section 40	DAMAGE TO FRONT BUMPER/NO PLATE & BONNET	46923	Damage	SKODA SUPERB ESTATE
00006801	07/01/2019	Section 40	Puncture	47619	Other	SKODA SUPERB ESTATE
00007202	03/02/2019	Section 40	Low Tread	50488	Repairs	SKODA SUPERB ESTATE
00007333	11/02/2019	Section 40	Tyre Damage	46035	Other	SKODA SUPERB ESTATE
00007919	18/03/2019	Section 40	knocking noise from rear wheel area when driving forward	54333	Breakdown	SKODA SUPERB ESTATE
			Road Test			
			Type 1 Light Vehicle Inspection-Type 1			
			Brake Pad Rear			

			Brake Disc Rear			
00008022	20/03/2019	Section 40	Windscreen	54333	Repairs	SKODA SUPERB ESTATE
00008959	15/05/2019	Section 40	DOG POD AIRCON SYSTEM US NOT BLOWING COLD AIR. THIS WIL NEED TO BE RECTIFIED A.S.A.P DUE TO HOT WEATHER.	59090	Breakdown	SKODA SUPERB ESTATE
00009162	24/05/2019	Section 40	Air blowing warm after 2-3 mins of operating	59657	Breakdown	SKODA SUPERB ESTATE
00009287	05/06/2019	Section 40	Air Conditioning Faulty	59832	Warranty Ext	SKODA SUPERB ESTATE
00010073	26/07/2019	Section 40	Air Conditioning Check temp in dog pods	60557	Other	SKODA SUPERB ESTATE
00010869	21/08/2019	Section 40	Top up	61101	Other	SKODA SUPERB ESTATE
00012269	20/11/2019	Section 40	intermittent engine management light.	62243	Breakdown	SKODA SUPERB ESTATE
00012422	20/11/2019	Section 40	Carry Out M.O.T-MOT Internal	62243	M.O.T.	SKODA SUPERB ESTATE

00012526	15/11/2019	Section 40	Tyre Damage	62243	Tyres	SKODA SUPERB ESTATE
00012552	26/11/2019	Section 40	Low Tread	62243	Tyres	SKODA SUPERB ESTATE
00013639	10/01/2020	Section 40	Oil service warning message has activated	63806	Breakdown	SKODA SUPERB ESTATE
			Brake Pad Rear			
			Fit mats to cages			
00013681	13/01/2020	Section 40	Type 2 Light Vehicle Inspection-Type 2	63806	Scheduled Maintenance	SKODA SUPERB ESTATE
00014524	12/02/2020	Section 40	MOT External	64011	M.O.T.	SKODA SUPERB ESTATE
00014827	25/02/2020	Section 40	HEADLIGHT AIM - right headlight bulb gone - Done @ Halfords	64326	Breakdown	SKODA SUPERB ESTATE
			In built Sat Nav not working correctly			
00015006	03/03/2020	Section 40	Front O/S Headlight	64405	Breakdown	SKODA SUPERB ESTATE
00015148	09/03/2020	Section 40	Air Conditioning check temp in dog pods	64405	Breakdown	SKODA SUPERB ESTATE

			Underside check following being towed on truck spec			
00016249	23/04/2020	Section 40	Check Battery	64326	Breakdown	SKODA SUPERB ESTATE
			Refit spare battery off workshop van			
00018000	30/06/2020	Section 40	Unplanned Roadside Recovery	66705	Breakdown	SKODA SUPERB ESTATE
00018002	30/06/2020	Section 40	Fit new Front N/S 1 Tyre Low Tread	66705	Tyres	SKODA SUPERB ESTATE
00018957	30/07/2020	Section 40	ADDITIONAL EQUIPMENT - Vehicle heating / aircon fans are not working - no air is being supplied to the vehicle and therefore no aircon is being supplied to the dog pods. This will make the vehicle US as dogs require the aircon.	69000	Breakdown	SKODA SUPERB ESTATE
			Check Air Conditioning Vehicle heating / aircon fans are not working - no air is being supplied to the vehicle and therefore no aircon is being supplied			
			CLUTCH SLIPPING - When in neutral - pressing the clutch down half way will cause a "crunching" noise of the gears.			

			Fit new Heater Motor			
			Fit new Clutch Assembly			
			Fit new Clutch Slave Cylinder			
			Fit new Flywheel			
			Fit new Flywheel Bolts			
00019692	27/08/2020	Section 40	Check Clutch Pedal went to the floor. You can lift it back up but there is no pressure. Clutch remains engaged.	70444	Repairs Ext	SKODA SUPERB ESTATE
00020494	17/09/2020	Section 40	Supply Rear N/S Tyre Damage	71500	Tyres	SKODA SUPERB ESTATE
00021650	09/11/2020	Section 40	WINDOWS - Window switches on drivers side are very temperamental. Sometimes they work fine, other time the windows wont open at all - tested them tonight and on one occasion they worked fine but all other occasions I struggled to open them /kept having to push the switch to open drivers window	75200	Breakdown	SKODA SUPERB ESTATE

			Check Window Regulator Window switches on drivers side are very temperamental. Sometimes they work fine, other time the windows wont open at all - tested them tonight			
			BODY - Underbody Cover keeps falling off, we think some of the clips are missing. We have slotted it back into place but may need re-clipping back on.			
			Check Undertray Underbody Cover keeps falling off, we think some of the clips are missing. We have slotted it back into place but may need re-clipping back on			
			RUN LOCK FAULT - When run lock Is activated - on a number of occasions now approx. 3 minuets after I get out of the vehicle, the engine will just cut out. When dog fans are running this is obviously going to cause us a battery issue at some point if we are away from vehicle for a long period of time.			
			Check Run Lock System When run lock Is activated - on a number of occasions now approx. 3 minuets after I get out of the vehicle, the engine will just cut out.			

00021651	09/11/2020	Section 40	ADDITIONAL EQUIPMENT - [Cant locate correct defect type] The pre-saved seat position settings have stopped working, this obviously comes standard on these skodas - not sure if this is a common issue. This vehicle is mainly only used by two handlers so if this can be fixed, it would be really useful.	75200	Breakdown	SKODA SUPERB ESTATE
			Check Seat he pre-saved seat position settings have stopped working, this obviously comes standard on these skodas - not sure if this is a common issue.			
00021652	09/11/2020	Section 40	Type 3 light Vehicle Inspection-Type 3	75779	Scheduled Maintenance	SKODA SUPERB ESTATE
00021699	10/11/2020	Section 40	Fit new Front Brake Discs and Pads	75779	Repairs	SKODA SUPERB ESTATE
			Fit new Rear Brake Discs and Pads			
			Fit new Rear Shock Absorber			
			Check Drivers window switch			
00021701	10/11/2020	Section 40	Supply Rear O/S 1 Tyre Punctured	75779	Tyres	SKODA SUPERB ESTATE
00021874	29/10/2020	Section 40	Supply Front O/S Tyre Punctured	75200	Tyres	SKODA SUPERB ESTATE

00023653	11/01/2021	Section 40	Supply Front 2 Tyre Low Tread	83388	Tyres	SKODA SUPERB ESTATE
00024324	10/02/2021	Section 40	Type 1 Light Vehicle Inspection-Type 1	86615	Scheduled Maintenance	SKODA SUPERB ESTATE
00024325	10/02/2021	Section 40	MOT Internal	86615	M.O.T.	SKODA SUPERB ESTATE
00024374	11/02/2021	Section 40	Supply Rear Tyre Low Tread	86615	Tyres	SKODA SUPERB ESTATE
00024373	11/02/2021	Section 40	Repair Rear N/S Rear Blues	86615	Repairs	SKODA SUPERB ESTATE
			Fit new Rear Reflector Lens			
			Fit new Hadex Oil Change			
			Check Key/Remote Fob			
			Fit new Rear Brake Discs and Pads			
			Fit new Front N/S Wheel Arch Liner			
00025876	27/03/2021	Section 40	Supply Front N/S 1 Tyre Punctured	92460	Tyres	SKODA SUPERB ESTATE
00025933	22/03/2021	Section 40	Supply Wiper Blades	93965		SKODA SUPERB ESTATE

00026289	26/04/2021	Section 40	ADDITIONAL EQUIPMENT - ***Vehicle due for a service *** Also, Issues with the Boot on the vehicle, when pressing to electronic boot closing button, the boot will lower but will not close fully and requires a physical push to shut it. Also, a recent defect has reoccurred, this relates to the pre-programmable driver seat positioning. When pressing the programmable buttons the seat is no longer moving to pre-set positioning. This is useful for when we require to deploy rapidly at the beginning of a shift.	95800	Breakdown	SKODA SUPERB ESTATE
00026566	05/05/2021	Section 40	Type 1 Light Vehicle Inspection-Type 1	97383	Scheduled Maintenance	SKODA SUPERB ESTATE
			Interior Sanitisation-Carry out Interior Sanitisation			
00026606	07/05/2021	Section 40	Fit new Front Brake Discs and Pads	97383	Repairs	SKODA SUPERB ESTATE
			Fit new Rear Brake Discs and Pads			
00026607	07/05/2021	Section 40	Supply Rear N/S 1 Tyre Punctured	97383	Tyres	SKODA SUPERB ESTATE
			Supply Front O/S Type Standard Tyre Low Tread			

00027284	19/05/2021	Section 40	External Body Repairs Front Bumper Refers ACC1212	97388	Damage	SKODA SUPERB ESTATE
00027377	11/06/2021	Section 40	ENGINE MANAGEMENT LAMP ILLUMINATED - light on	97547	Repairs Ext	SKODA SUPERB ESTATE
			Check Engine Management Light light on			
			DOOR / BOOT / CAGE / CELL LOCK FAULTY - boot keeps on closing of its own accord once opened and nearly trapped the police dog in the process. was "fixed" a few days previous.			
			Check Boot Release boot keeps on closing of its own accord once opened and nearly trapped the police dog in the process. was "fixed" a few days previous.			
			Interior Sanitisation-Carry out Interior Sanitisation			
00027421	14/06/2021	Section 40	Check Air Conditioning	97547	Scheduled Maintenance	SKODA SUPERB ESTATE
00028517	15/07/2021	Section 40	Supply Rear O/S 1 Tyre Damage	98247	Tyres	SKODA SUPERB ESTATE

00029536	10/09/2021	Section 40	Check Handbrake when handbrake applied when clutch pedal released handbrake comes off	102393	Repairs	SKODA SUPERB ESTATE
00031195	22/11/2021	Section 40	Check Brakes brakes grinding	106860	Breakdown	SKODA SUPERB ESTATE
00031196	22/11/2021	Section 40	Type 3 light Vehicle Inspection-Type 3	106860	Scheduled Maintenance	SKODA SUPERB ESTATE
00031221	23/11/2021	Section 40	Fit new Front Wiper Blades	106860	Repairs	SKODA SUPERB ESTATE
			Check Gearbox Support Mounting			
			Replace Front Brake Pads			
			Replace Rear Brake Discs			
			Replace Rear Brake Pads			
00031226	23/11/2021	Section 40	Supply All Tyre Low Tread	106860	Tyres	SKODA SUPERB ESTATE
00032228	14/12/2021	Section 40	Supply Front N/S 1 Tyre Punctured	108248	Tyres	SKODA SUPERB ESTATE
00032586	20/01/2022	Section 40	Vehicle Recovery recovered	108583	Damage	SKODA SUPERB ESTATE
			Front Misc Body damage			
			Supply new Front Grille Lights			
00033734	09/02/2022	Section 40	Supply Front O/S Tyre Damage	108900	Tyres	SKODA SUPERB ESTATE

00035069	03/05/2022	Section 40	Check Boot Release The boot release on the boot itself, and also using the key remotely appear to have about a 1 in 10 chance of releasing	110030	Breakdown	SKODA SUPERB ESTATE
00036091	05/06/2022	Section 40	Supply Front N/S 1 Tyre Punctured	110774	Tyres	SKODA SUPERB ESTATE
00036442	04/07/2022	Section 40	FLAT BATTERY - Engine will not start, Aux equipment is not working, boot wont open etc - believe this will be a Power issue. Vehicle at HQ -Dog Support	112450	Breakdown	SKODA SUPERB ESTATE
			Check Starter System ux equipment is not working, boot wont open etc - believe this will be a Power			
00037975	07/09/2022	Section 40	Type 1 Light Vehicle Inspection-Type 1	119618	Scheduled Maintenance	SKODA SUPERB ESTATE
00037976	07/09/2022	Section 40	Fit new Cambelt Replacement	119618	Scheduled Maintenance	SKODA SUPERB ESTATE
00038120	13/09/2022	Section 40	Check Front Washer Jets in-op	119618	Repairs	SKODA SUPERB ESTATE
			Fit new Wiper Blades Front			
			Replace O/S/R Brake Backplate			

			Fit new Brake Discs Front			
			Fit new Brake Pads Front			
			Fit new Brake Pads Rear			
			Fit new Exhaust Sensor - DPF pressure sensor			
00038126	13/09/2022	Section 40	Supply Front 2 Tyre Low Tread	119618	Tyres	SKODA SUPERB ESTATE
			Supply Rear N/S 1 Tyre Low Tread			
00039570	28/10/2022	Section 40	Supply Light Bulb	122885		SKODA SUPERB ESTATE
00040392	19/12/2022	Section 40	ENGINE MANAGEMENT LAMP ILLUMINATED - Battery Fault warning for battery and engine management light on	125668	Repairs	SKODA SUPERB ESTATE
			Check Engine Management Light Fault warning for battery and engine management light on			
			Fit new Rear Boot Release Switch			
			Fit new Alternator			
00040777	05/01/2023	Section 40	ENGINE MANAGEMENT LAMP ILLUMINATED - Engine Management Light Engine light illuminated, vehicle also juddering and vibrating through floor, clutch and steering at low speed.	125960	Repairs	SKODA SUPERB ESTATE

			Check Engine Management Light Engine light illuminated, vehicle also juddering and vibrating through floor, clutch and steering at low speed.			
00041261	26/01/2023	Section 40	Check Engine Management Light the engine management light is back on and it is running very rough.	126459	Repairs	SKODA SUPERB ESTATE
			Fit new DPF			
			Fit new EGR Valve			
			Fit new Front O/S Anti Roll Bar Drop Link			
			Fit new Front Wishbones O/S And N/S			
			Fit new Coolant Hose			
00042139	06/03/2023	Section 40	Supply Front 2 Tyre Low Tread	126459	Tyres	SKODA SUPERB ESTATE
00042777	03/04/2023	Section 40	BRAKES GRINDING - Faults Whilst driving the car is making a constant squeaking and grinding noise and when the car is stationary in traffic the engine sounds like it rattles and sounds like it is struggling to tick over.	128681	Breakdown	SKODA SUPERB ESTATE
00042881	06/04/2023	Section 40	Type 1 Light Vehicle Inspection-Type 1	128681	Scheduled Maintenance	SKODA SUPERB ESTATE
			Fit new Front Wiper Blades			

			Fit new Front O/S Fog Light			
			Fit new Front Brake Pads			
			Fit new Rear Brake Discs and Pads			
			Fit new Rear Rear Halex Oil			
00043215	10/04/2023	Section 40	Accident Damage to Rear Bumper	128681	Damage	SKODA SUPERB ESTATE
00043901	22/05/2023	Section 40	ENGINE NOISE - Faults No faults showing however while vehicle is in in for another fault can someone look at or listen to how the car sounds from the engine as it grumbles and judders which feels like the car struggles.	129491	Repairs	SKODA SUPERB ESTATE
			Fit new Clutch Assembly Plus Bolts			
			Fit new Clutch Slave Cylinder			
			Fit new Flywheel Plus Bolts			
			Check Top up Gearbox Oil			
00043902	22/05/2023	Section 40	DOOR / BOOT / CAGE / CELL LOCK FAULTY - Air Conditioning On this vehicle it feels like the air con that flows into the dog cages is coming out however doesn't feel like it is blowing cold and the dogs are coming out hot.	129491	Repairs	SKODA SUPERB ESTATE
			Check Air Conditioning Air Conditioning			

			Check Air Conditioning in dog pod			
00044120	30/05/2023	Section 40	Supply Rear N/S Tyre Low Tread	129546	Tyres	SKODA SUPERB ESTATE
			Supply Rear O/S Tyre Punctured			
00044450	14/06/2023	Section 40	ADDITIONAL EQUIPMENT - Tyre Pressure Tyre pressure indicator is showing a fault and the sensor is not working no issues with the tyres or the pressure. Tyre pressure indicator is showing a fault and the sensor is not working no issues with the tyres or the pressure.	129866	Repairs	SKODA SUPERB ESTATE
00045500	04/08/2023	Section 40	BRAKES GRINDING - Brake Discs and Pads Front brakes are grinding but do stop the vehicle.	133083	Breakdown	SKODA SUPERB ESTATE
			Check Brakes Brake Discs and Pads Front brakes are grinding but do stop the vehicle.			
			Fit new Rear Brake Discs and Pads			
			Fit new Gear Cable Bush			
00046556	21/09/2023	Section 40	Check Dog Pod n/s dog podhas been chewed	134945	Damage	SKODA SUPERB ESTATE

00046843	09/10/2023	Section 40	Check Brakes The rear brakes or bearings are making a horrendous scraping sound and the vehicle is unsafe to drive.	134944	Repairs	SKODA SUPERB ESTATE
			Fit new Rear Brake Discs and Pads			
			Fit new Rear N/S Brake Caliper			
			Fit new Rear N/S Brake Pipe / Flexi Hose			
00047061	30/09/2023	Section 40	Supply Top up AdBlue	134944		SKODA SUPERB ESTATE
00048350	11/12/2023	Section 40	COOLANT WARNING LAMP - Dashboard Warning Lights	137000	Repairs	SKODA SUPERB ESTATE
			Check Dashboard Warning Lights Coolant warning on dash			
			Fit new Inner Boot Release Switch			
			Fit new EGR Cooler			
			Fit new Fuel Injector Seals			
00048398	26/11/2023	Section 40	Supply Rear O/S 1 Tyre Punctured	137000	Tyres	SKODA SUPERB ESTATE
00048399	27/11/2023	Section 40	Supply Front 2 Tyre Low Tread	137000	Tyres	SKODA SUPERB ESTATE
			Supply Rear N/S 1 Tyres			
00049329	30/01/2024	Section 40	Type 3 light Vehicle Inspection - Type 3	139064	Scheduled Maintenance	SKODA SUPERB ESTATE

			Check O/S Blue mirror light inop			
			Fit new Front O/S Door Lock cap			
			Check O/S Rear Blue inop			
			Check Rear N/S back plate			
			Check heat sheild loose			
00049387	31/01/2024	Section 40	Supply Front N/S 1 Tyre Low Tread	139064	Tyres	SKODA SUPERB ESTATE
00049680	23/06/2023	Section 40	Supply Rear O/S Tyre Punctured	139064	Tyres	SKODA SUPERB ESTATE
00050158	04/03/2024	Section 40	DRIVE TRAIN FAULT - Drive Train Loud banging under the car when turning the wheel unsure if anything is hanging off under the car or what is causing the noise.	141804	Repairs	SKODA SUPERB ESTATE
			Check Suspension Drive Train Loud banging under the car when turning the wheel unsure if anything is hanging off under the car or what is causing the noise.			
			Collect & Deliver Collect or Return Vehicle Stafford			
			Fit new Front Spring			
			Fit new Front Strut Top Mounting Plus Bolts			
00050512	13/03/2024	Section 40	Supply Headlight	141804		SKODA SUPERB ESTATE

00050635	21/02/2024	Section 40	Supply Front N/S Tyre Punctured	141804	Tyres	SKODA SUPERB ESTATE
00051591	01/05/2024	Section 40	Check Battery Unable to start	142200	Repairs	SKODA SUPERB ESTATE
00051629	02/05/2024	Section 40	FLAT BATTERY - The car will not tick over and no electrics are working - fault started 1/5/24 but was jump started but clearly not holding any charge. Miles not correct on report due to nothing coming on internally in the car to get correct miles.	142314	Repairs	SKODA SUPERB ESTATE
			Check Air Conditioning ini dog pod			
00052005	21/05/2024	Section 40	Check Dog Pod We have a damaged dog pod, it's in the roof of the right pod, there is a vertical section towards the gate end of the pod.	143053	Repairs	SKODA SUPERB ESTATE
			Check Engine Management Light			
00038434	19/08/2022	Section 40	Supply Rear O/S 1 Tyre Punctured	118160	Tyres	SKODA SUPERB ESTATE
00037787	24/08/2022	Section 40	Fit new Front Windscreen	95214	Windscreen	SKODA SUPERB ESTATE
00036949	25/07/2022	Section 40	BRAKES LOW EFFORT - Brake Discs and Pads rear brakes are grinding	114058	Breakdown	SKODA SUPERB ESTATE
			Check Brakes rear brakes are grinding			

00036672	13/07/2022	Section 40	Check Air Conditioning in Dog pod	112611	Scheduled Maintenance	SKODA SUPERB ESTATE
00005532	29/10/2018	Section 40	Warning light for front sensor being obscured illuminates. Whilst driving along the safety feature also activates and brakes the car automatically for no reason.	46923	Breakdown	SKODA SUPERB ESTATE
			Air conditioning may need re-gassing. Appears to be not as efficient at clearing the screen.			
			Sound of 'slushing' water coming from rear of cab near or under the dog pods. It is not the water bottle used for the dog as it was still making the noise when turning even when the bottle was empty or out of the car. Water ingress from washing??			