

<u>Job Number</u>	<u>Odo Reading</u>	<u>Job Date</u>	<u>Work Detail Description</u>	<u>Workshop Job Sheet Type</u>	<u>Registration Number</u>
00002612	17030	25/04/2018	Low Tread	Repairs	SECTION 40

00003306	18900	12/06/2018	Type 1 Light Vehicle Inspection- Type 1 Safety Inspection. Oil & Filter.	Scheduled Maintenance	SECTION 40
			Windscreen Washers		
			Rear Disc's and Pads		
			Road Test		

00008415	30089	15/04/2019	Type 2 Light Vehicle Inspection- Type 2	Scheduled Maintenance	SECTION 40
			Check cooling system for leaks.		
			Change speaker		
			Replace Front Front Disc's and pads		
			Low Tread		

00008435	30089	16/04/2019	Thermostat Housing Leaking	Warranty Ext	SECTION 40
----------	-------	------------	----------------------------	--------------	------------

00009065	30923	22/05/2019	Heater system Fan only works on full	Warranty Ext	SECTION 40
			Vehicle will not start		

00009571	31768	25/06/2019	MOT Internal	Scheduled Maintenance	SECTION 40
----------	-------	------------	--------------	-----------------------	------------

00014385	40743	07/02/2020	Type 3 light Vehicle Inspection- Type 3	Scheduled Maintenance	SECTION 40
----------	-------	------------	--	-----------------------	------------

00014450	40743	11/02/2020	Low Tread	Tyres	SECTION 40
----------	-------	------------	-----------	-------	------------

00014578	40743	14/02/2020	Road wheel	Repairs	SECTION 40
----------	-------	------------	------------	---------	------------

00016692	44328	11/05/2020	ENGINE MANAGEMENT LAMP ILLUMINATED - miss firing	Breakdown	SECTION 40
			Unplanned Collect or Return Vehicle		

00000282	11156	14/12/2017	Water bottle motor not working correctly - not releasing the liquid	Breakdown	SECTION 40
----------	-------	------------	---	-----------	------------

00017584	0	15/06/2020	MOT Internal	M.O.T.	SECTION 40
----------	---	------------	--------------	--------	------------

00016692	44328	11/05/2020	Warranty Repair Check	Breakdown	SECTION 40
			Carry out Road Test		

00019110	45557	23/07/2020	Supply Rear O/S Tyre Damage	Tyres	SECTION 40
----------	-------	------------	-----------------------------	-------	------------

00021670	49500	14/10/2020	Supply Front N/S Tyre Punctured	Tyres	SECTION 40
----------	-------	------------	---------------------------------	-------	------------

00021682	50201	09/11/2020	Type 1 Light Vehicle Inspection- Type 1	Scheduled Maintenance	SECTION 40
----------	-------	------------	--	-----------------------	------------

00021746	50201	11/11/2020	Fit new Front Brake Pads	Repairs	SECTION 40
			Fit new Rear Brake Pads		

00021760	50201	11/11/2020	Check Locking Wheel Stud/Nuts	Repairs	SECTION 40
			Fit new Rear Brake Discs and Pads		

00024687	53814	25/02/2021	Fit new Wiper Blades	Breakdown	SECTION 40
----------	-------	------------	----------------------	-----------	------------

00025204	54526	01/03/2021	Supply Front 2 Tyre Punctured	Tyres	SECTION 40
			Supply Rear N/S 1 Tyre Low Tread		

00027665	55827	22/06/2021	Interior Sanitisation-Carry out Interior Sanitisation	M.O.T.	SECTION 40
			MOT Internal		

00030019	59254	24/09/2021	Repair AirWave Fault	Commissioning Repairs	SECTION 40
00032303	62716	12/01/2022	Type 1 Light Vehicle Inspection- Type 1	Scheduled Maintenance	SECTION 40
00032410	62716	14/01/2022	Check & Adjust Rear Handbrake	Repairs	SECTION 40
			Fit new Front Strut Top Mounting		
			Check & Adjust Rear Number Plate Mount		
			Fit new Front Brake Discs and Pads		
00036406	69825	30/06/2022	MOT Internal	M.O.T.	SECTION 40
00036420	69825	30/06/2022	Fit new All Tyre Low Tread	Tyres	SECTION 40
00037184	71023	14/07/2022	Supply Front N/S Tyre Damage	Tyres	SECTION 40
00037452	72771	11/08/2022	Fit new Front Windscreen	Windscreen	SECTION 40
00038031	73898	08/09/2022	Type 3 light Vehicle Inspection- Type 3	Scheduled Maintenance	SECTION 40
00039538	77485	09/11/2022	ADDITIONAL EQUIPMENT - Heater System Cabin heater is not blowing hot air.	Repairs	SECTION 40
00040014	77527	01/12/2022	Check Heater System Heaters still not getting hot	Repairs	SECTION 40
00041010	78676	04/01/2023	Supply All 4 Tyres	Tyres	SECTION 40
00041461	79577	03/02/2023	Fit new Windscreen	Windscreen	SECTION 40

00042209	80759	08/03/2023	Check Auxiliary Socket When a charging device is plugged in it will illuminate to show that it is receiving power, but when an electronic device is plugged in it will not charge the device	Repairs	SECTION 40
----------	-------	------------	--	---------	------------

00043828	84945	18/05/2023	Type 1 Light Vehicle Inspection- Type 1	Scheduled Maintenance	SECTION 40
			MOT Internal		
			Check Heater System Heater in car not working again		

00043847	84287	05/05/2023	Supply Front 2 Tyre Low Tread	Tyres	SECTION 40
----------	-------	------------	-------------------------------	-------	------------

00043828	84945	18/05/2023	Fit new Front Brake Discs and Pads	Scheduled Maintenance	SECTION 40
			Fit new Rear Brake Discs and Pads		
			Fit new Both Track Control Arm (Front Lower)		
			Fit new Heater Matrix		
			Fit new Radiator		
			Fit new Coolant Supply Pump		

00045355	88116	28/07/2023	Check Suspension bad knocking and scraping sound coming from the front of the car. Its worse at low speeds and has gotten progressive worse of the last few week to the point where now its making steering wheel shake	Repairs	SECTION 40
			Collect & Deliver Collect or Return Vehicle		

00047101	92983	19/10/2023	Check Cooling System leaking coolant.	Repairs	SECTION 40
			Collect & Deliver Collect or Return Vehicle HQ		