

<u>Job Number</u>	<u>Latest Distance</u>	<u>Date In</u>	<u>Vehicle Asset.Registration Number</u>	<u>Job Description</u>	<u>Workshop Job Sheet.Workshop Job Sheet Type</u>	<u>Allocation on Job Date.Vehicle Asset.Make Model Derivative</u>
00001193	26933	10/02/2018	SECTION 40	Response Service 2-Type 1	Scheduled Maintenance	PEUGEOT EXPERT 110 PANEL VAN
				MOT External		

00007149	28037	31/01/2019	SECTION 40	MOT Internal		PEUGEOT EXPERT 110 PANEL VAN
				Type 2 Light Vehicle Inspection-Type 2		PEUGEOT EXPERT 110 PANEL VAN

00007105	28831	01/02/2019	SECTION 40	Type 2 Light Vehicle Inspection-Type 2	Scheduled Maintenance	PEUGEOT EXPERT 110 PANEL VAN
				MOT Internal		
				Front Disc's and pads		
				Brake Shoes		
				MAKE REPAIR TO FRONT N/S BUMPER.		
				REPLACE FRONT INDICATOR BULBS.		

00008104	28917	29/03/2019	SECTION 40	Exhaust Pipe exhaust blowing	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	------------------------------	-----------	---------------------------------

00009140	28931	29/05/2019	SECTION 40	Exhaust Pipe Come loose	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	-------------------------	-----------	---------------------------------

00009493	29121	19/06/2019	SECTION 40	Battery turn's over wont start	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--------------------------------	-----------	---------------------------------

00010111	29233	29/07/2019	SECTION 40	Exhaust Noisy	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
				Keeps cutting out		

00010937	30000	12/09/2019	SECTION 40	Engine turns over but wont start, identical symptoms to a fault which was rectified 2 months ago.	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	---	-----------	---------------------------------

00014257	30107	04/02/2020	SECTION 40	Type 3 light Vehicle Inspection-Type 3	Scheduled Maintenance	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--	--------------------------	---------------------------------

00014258	30107	04/02/2020	SECTION 40	MOT external	M.O.T.	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--------------	--------	---------------------------------

00014540	30107	12/02/2020	SECTION 40	Replace front Wiper Blade	Repairs	PEUGEOT EXPERT 110 PANEL VAN
				Check and clean off overspilt oil		

00015814	30933	06/04/2020	SECTION 40	Check Radiator Possible leak. Warning light on dash	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
				Cambelt replacement		

00018462	30993	13/07/2020	SECTION 40	Check Exhaust System Exhaust has fallen off	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	---	-----------	---------------------------------

00024254	32233	08/02/2021	SECTION 40	Type 1 Light Vehicle Inspection-Type 1	Scheduled Maintenance Ext	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--	------------------------------	---------------------------------

00024255	32233	08/02/2021	SECTION 40	MOT External	M.O.T.	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--------------	--------	---------------------------------

00033099	35350	08/02/2022	SECTION 40	Type 1 Light Vehicle Inspection-Type 1	Scheduled Maintenance Ext	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--	------------------------------	---------------------------------

00033100	35350	08/02/2022	SECTION 40	MOT External	M.O.T.	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--------------	--------	---------------------------------

00038006	35391	08/09/2022	SECTION 40	SUSPENSION - Suspension Front N/S spring has broken, vehicle is un driveable. Keys will be left in Rugeley front office for JETS attention.	Breakdown	PEUGEOT EXPERT 110 PANEL VAN
				Check Suspension Front N/S spring has broken, vehicle is un driveable.		

00038113	35391	12/09/2022	SECTION 40	Supply Front 2 Tyre Low Tread	Tyres	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	-------------------------------	-------	---------------------------------

00038208	35391	16/09/2022	SECTION 40	Check Misc Body Damage to roof	Damage	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--------------------------------	--------	---------------------------------

00040186	35733	09/12/2022	SECTION 40	CABIN HEATER DE-MIST - Heater System Vans heater does not work windscreen can not be cleared, unsafe to drive. Also there is a substantial leak from the bottom left hand screen area which results in the massive puddle around your feet when it rains. Video obtained and emailed to JETS. Vehicle is UNSAFE	Repairs Ext	PEUGEOT EXPERT 110 PANEL VAN
----------	-------	------------	------------	--	-------------	---------------------------------

Check Heater System Vans heater does
not work windscreen can not be cleared,
unsafe to drive. Also there is a substantial
leak from the bottom left ha

Collect & Deliver Collect or Return Vehicle
Rugeley

00041046	35733	17/01/2023	SECTION 40	Type 3 light Vehicle Inspection-Type 3 External	Scheduled Maintenance Ext	PEUGEOT EXPERT 110 PANEL VAN
				MOT External		