

Vehicle Service History

Job Number	Vehicle Registration Number	Date In	Job Description	Latest Distance	Workshop Job Sheet Type	Vehicle Make Model Derivative
00014576	Withheld, section 40	14/02/2020	Low Tread	3221	Tyres	SKODA OCTAVIA ESTATE
00015181	Withheld, Section 40	11/03/2020	Top Up Oil	3250	Breakdown	SKODA OCTAVIA ESTATE
00016452	Withheld, Section 40	19/06/2020	Type 1 Light Vehicle Inspection-Type 1	7355	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00017730	Withheld, Section 40	22/06/2020	Fit new Front Brake Pads	3221	Repairs	SKODA OCTAVIA ESTATE
00018952	Withheld, Section 40	09/07/2020	Remove & Refit Windscreen	3221	Windscreen	SKODA OCTAVIA ESTATE
00020027	Withheld, Section 40	05/09/2020	Unplanned Roadside Recovery	8534	Breakdown	SKODA OCTAVIA ESTATE
00020287	Withheld, Section 40	15/09/2020	Supply Front O/S Tyre Low Tread	8534	Tyres	SKODA OCTAVIA ESTATE
00021185	Withheld, Section 40	15/10/2020	Fit new Windscreen	3221	Windscreen	SKODA OCTAVIA ESTATE

00021620	Withheld, Section 40	06/11/2020	Check Cooling System User reports loss of Fit new Thermostat Housing Fit new Throttle Body Housing Gasket Fit new Coolant Pump Gasket And belt	11561	Breakdown	SKODA OCTAVIA ESTATE
00022993	Withheld, Section 40	14/12/2020	Supply Rear O/S 1 Tyre Punctured	15232	Tyres	SKODA OCTAVIA ESTATE
00023822	Withheld, Section 40	31/12/2020	Supply Front O/S 1 Tyre Damage	16713	Tyres	SKODA OCTAVIA ESTATE
00023966	Withheld, Section 40	23/01/2021	Supply Front N/S 1 Tyre Damage	18830	Tyres	SKODA OCTAVIA ESTATE
00024264	Withheld, Section 40	08/02/2021	Type 1 Light Vehicle Inspection-Type 1	20821	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00024288	Withheld, Section 40	09/02/2021	Fit new Front Brake Pads	20821	Repairs	SKODA OCTAVIA ESTATE
00024289	Withheld, Section 40	09/02/2021	Supply Rear N/S 1 Tyre Low Tread	20821	Tyres	SKODA OCTAVIA ESTATE
00025109	Withheld, Section 40	08/01/2021	Supply Front N/S 1 Tyre Low Tread	17188	Tyres	SKODA OCTAVIA ESTATE
00025159	Withheld, Section 40	28/02/2021	Supply Rear O/S 1 Tyre Punctured	23170	Tyres	SKODA OCTAVIA ESTATE

00025665	Withheld, Section 40	05/03/2021	Supply Front O/S 1 Tyre Punctured	23663	Tyres	SKODA OCTAVIA ESTATE
00025844	Withheld, Section 40	06/04/2021	Supply Front 2 Tyre Low Tread	27186	Tyres	SKODA OCTAVIA ESTATE
00026656	Withheld, Section 40	10/05/2021	Type 3 light Vehicle Inspection-Type 3	30840	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00026683	Withheld, Section 40	11/05/2021	Fit new Front Brake Discs and Pads	30840	Repairs	SKODA OCTAVIA ESTATE
00026894	Withheld, Section 40	20/05/2021	POOR STARTING - Vehicle won't start when turned by key	30870	Breakdown	SKODA OCTAVIA ESTATE
00027212	Withheld, Section 40	04/06/2021	Fit new Wheel Trim - Centre caps	33087	Repairs	SKODA OCTAVIA ESTATE
00027258	Withheld, Section 40	23/05/2021	Supply Rear N/S 1 Tyre Punctured	33087	Tyres	SKODA OCTAVIA ESTATE
00027774	Withheld, Section 40	23/06/2021	Fit new Windscreen	34383	Windscreen	SKODA OCTAVIA ESTATE
00029007	Withheld, Section 40	18/08/2021	Check Reverse Light Bulb requires replacing. Connection rusty possible water ingress	35690	Breakdown	SKODA OCTAVIA ESTATE
00029144	Withheld, Section 40	24/08/2021	External Body Repairs Damage to Bonnet	35690	Damage	SKODA OCTAVIA ESTATE
00029152	Withheld, Section 40	11/08/2021	Supply Front 2 Tyre Punctured	34863	Tyres	SKODA OCTAVIA ESTATE

00029418	Withheld, Section 40	06/09/2021	Fit new Tint Windows	36001	Other	SKODA OCTAVIA ESTATE
00030599	Withheld, Section 40	10/10/2021	Supply Front O/S 1 Tyre Damage	40248	Tyres	SKODA OCTAVIA ESTATE
00030648	Withheld, Section 40	29/10/2021	Type 1 Light Vehicle Inspection-Type 1	42527	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00030666	Withheld, Section 40	01/11/2021	Replace Front Brake Pads	42527	Repairs	SKODA OCTAVIA ESTATE
00030667	Withheld, Section 40	01/11/2021	Replace Front Tyres-Potteries Tyres	42527	Tyres	SKODA OCTAVIA ESTATE
00030668	Withheld, Section 40	01/11/2021	Supply Front O/S 1 Tyre Low Tread	42527	Tyres	SKODA OCTAVIA ESTATE
00031938	Withheld, Section 40	15/12/2021	Supply Front O/S 1 Tyre Punctured	47135	Tyres	SKODA OCTAVIA ESTATE
00032832	Withheld, Section 40	31/01/2022	Check Reversing Aid Reversing Aid parking sensors showing an error and not working	52301	Breakdown	SKODA OCTAVIA ESTATE
00032839	Withheld, Section 40	31/01/2022	Type 1 Light Vehicle Inspection-Type 1	52318	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00032846	Withheld, Section 40	31/01/2022	Supply Rear N/S 1 Tyre Punctured	52318	Tyres	SKODA OCTAVIA ESTATE
00032848	Withheld, Section 40	31/01/2022	Fit new Front Brake Pads	52318	Repairs	SKODA OCTAVIA ESTATE

00033265	Withheld, Section 40	19/01/2022	Supply Front N/S 1 Tyre Low Tread	50685	Tyres	SKODA OCTAVIA ESTATE
00033780	Withheld, Section 40	08/02/2022	Supply Rear O/S 1 Tyre Punctured	53176	Tyres	SKODA OCTAVIA ESTATE
00033802	Withheld, Section 40	09/03/2022	Supply Fit Floor Mats Replacement floor mats. Old ones have become worn and are getting trapped under the pedals.	53779	Other	SKODA OCTAVIA ESTATE
00034176	Withheld, Section 40	02/03/2022	Supply Front O/S 1 Tyre Damage	53891	Tyres	SKODA OCTAVIA ESTATE
00035010	Withheld, Section 40	31/01/2022	WARNING LIGHT - Reversing Aid parking sensors showing an error and not working	52301		SKODA OCTAVIA ESTATE
00036299	Withheld, Section 40	27/06/2022	WARNING LIGHT - Brake Discs and Pads BRAKE WARE WARNING LIGHT ON DASH	62613	Breakdown	SKODA OCTAVIA ESTATE
00036306	Withheld, Section 40	27/06/2022	Type 3 light Vehicle Inspection-Type 3	62613	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00036328	Withheld, Section 40	27/06/2022	Supply Front Tyre Low Tread	62613	Tyres	SKODA OCTAVIA ESTATE
00036331	Withheld, Section 40	27/06/2022	Fit new Rear Wiper Blades	62613	Repairs	SKODA OCTAVIA ESTATE
00037428	Withheld, Section 40	15/08/2022	Check Top up Engine Oil	66773	Repairs	SKODA OCTAVIA ESTATE
00038247	Withheld, Section 40	20/09/2022	BRAKES LOW EFFORT - Brake ABS Sensor Brake sensor light is illuminated * Also service light illuminated too	73427	Breakdown	SKODA OCTAVIA ESTATE

00038299	Withheld, Section 40	20/09/2022	Type 1 Light Vehicle Inspection-Type 1	73427	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00038374	Withheld, Section 40	22/09/2022	Check drivers Seat back torn	73427	Repairs	SKODA OCTAVIA ESTATE
00038384	Withheld, Section 40	16/08/2022	Supply Front O/S 1 Tyre Punctured	66631	Tyres	SKODA OCTAVIA ESTATE
00038385	Withheld, Section 40	19/08/2022	Supply Front N/S 1 Tyre Low Tread	69049	Tyres	SKODA OCTAVIA ESTATE
00038563	Withheld, Section 40	27/07/2022	Supply Rear N/S Tyre Punctured	73941	Tyres	SKODA OCTAVIA ESTATE
00038850	Withheld, Section 40	07/09/2022	Supply Rear N/S 1 Tyre Punctured	71843	Tyres	SKODA OCTAVIA ESTATE
00041044	Withheld, Section 40	28/12/2022	Supply Front 2 Tyre Low Tread	76657	Tyres	SKODA OCTAVIA ESTATE
00041064	Withheld, Section 40	18/01/2023	Check Cooling System Vehicle overheating and heaters not working	80247	Repairs	SKODA OCTAVIA ESTATE
00041105	Withheld, Section 40	03/01/2023	Supply Front O/S Tyre Punctured	80247	Tyres	SKODA OCTAVIA ESTATE
00042171	Withheld, Section 40	07/03/2023	Check Heater System that it has no heating whatsoever. Even on high for a prolonged period of time it only blows out cold air.	81832	Repairs	SKODA OCTAVIA ESTATE

00042206	Withheld, Section 40	08/03/2023	Type 3 light Vehicle Inspection-Type 3	81832	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00042245	Withheld, Section 40	09/03/2023	Supply Front N/S 1 Tyre Damage	81832	Tyres	SKODA OCTAVIA ESTATE
00043391	Withheld, Section 40	02/05/2023	WARNING LIGHT - Brake Pads brake pad warning light	86032	Repairs	SKODA OCTAVIA ESTATE
00043482	Withheld, Section 40	12/04/2023	Supply Rear N/S 1 Tyre Damage	85306	Tyres	SKODA OCTAVIA ESTATE
00043545	Withheld, Section 40	13/04/2023	Supply Front N/S Tyre Damage	86032	Tyres	SKODA OCTAVIA ESTATE
00043687	Withheld, Section 40	19/04/2023	Supply Front 2 Tyre Damage	85452	Tyres	SKODA OCTAVIA ESTATE
00043961	Withheld, Section 40	12/05/2023	Supply Front N/S 1 Tyre Punctured	87004	Tyres	SKODA OCTAVIA ESTATE
00044377	Withheld, Section 40	09/06/2023	Fit new Rear N/S Wheel	88512	Damage	SKODA OCTAVIA ESTATE
00044378	Withheld, Section 40	09/06/2023	Supply Front Tyre Low Tread	88512	Tyres	SKODA OCTAVIA ESTATE
00044378	Withheld, Section 40	09/06/2023	Supply Rear N/S Tyre Punctured	88512	Tyres	SKODA OCTAVIA ESTATE
00044466	Withheld, Section 40	09/06/2023	Check Engine Level Fault	88512	Breakdown	SKODA OCTAVIA ESTATE

00047632	Withheld, Section 40	10/11/2023	Type 1 Light Vehicle Inspection - Type 1	90823	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00047848	Withheld, Section 40	19/10/2023	Supply Front O/S 1 Tyre Damage	90335	Tyres	SKODA OCTAVIA ESTATE
00048705	Withheld, Section 40	02/01/2024	Supply N/S Tyre Damage	93834	Damage	SKODA OCTAVIA ESTATE
00048867	Withheld, Section 40	14/12/2023	Supply Front N/S Tyre Punctured	93834	Tyres	SKODA OCTAVIA ESTATE
00049391	Withheld, Section 40	31/01/2024	Check Dashboard Warning Lights The fault is a red warning triangle appearing on the dash impermanently and saying 12 volt battery not charging.	97280	Breakdown	SKODA OCTAVIA ESTATE
00049400	Withheld, Section 40	04/01/2024	Supply Front N/S 1 Tyre Damage	94729	Tyres	SKODA OCTAVIA ESTATE
00049457	Withheld, Section 40	05/02/2024	SEAT BELTS / SEATS - Seat Drivers seat is ripped and has split at the seam and as a result the inner foam is showing.	97600	Repairs	SKODA OCTAVIA ESTATE
00049458	Withheld, Section 40	05/02/2024	BRAKES LOW EFFORT - Brake Discs and Pads Brake pad warning light has come on.	97280	Repairs	SKODA OCTAVIA ESTATE
00049865	Withheld, Section 40	29/01/2024	Supply Front O/S Tyre Low Tread	98214	Tyres	SKODA OCTAVIA ESTATE
00050247	Withheld, Section 40	06/03/2024	Type 1 Light Vehicle Inspection - Type 1	100502	Scheduled Maintenance	SKODA OCTAVIA ESTATE

00050290	Withheld, Section 40	08/03/2024	Supply All Tyre Low Tread	100502	Tyres	SKODA OCTAVIA ESTATE
00051342	Withheld, Section 40	27/03/2024	Supply Front N/S 1 Tyre Punctured	108402	Tyres	SKODA OCTAVIA ESTATE
00051406	Withheld, Section 40	24/04/2024	Type 1 Light Vehicle Inspection - Type 1	108813	Scheduled Maintenance	SKODA OCTAVIA ESTATE
00051528	Withheld, Section 40	16/04/2024	Supply Front O/S 1 Tyre Low Tread	108813	Tyres	SKODA OCTAVIA ESTATE
00051739	Withheld, Section 40	08/05/2024	OIL LEVEL - Top up Engine Oil - Reoccurring problem with vehicle losing Oil and burning smell from engine inside the vehicle, especially under hard acceleration. Checked the dip stick and there is only a small amount showing at the very bottom of the marker. This has completely emptied in a week since collecting from Jets No loss of power or performance issues. However taken off the road due to above issue.	110340	Repairs	SKODA OCTAVIA ESTATE
00051819	Withheld, Section 40	13/05/2024	DASH WARNING LIGHTS - airbag warning light illuminated	111753	Repairs	SKODA OCTAVIA ESTATE
00052351	Withheld, Section 40	08/05/2024	Supply Front N/S 1 Tyre Low Tread	114989	Tyres	SKODA OCTAVIA ESTATE
00052413	Withheld, Section 40	10/06/2024	OIL LEVEL - Top up Engine Oil - Oil warning light on and no Oil showing on the dip stick when checked. vehicle now off the Road	115655	Repairs	SKODA OCTAVIA ESTATE

00054942	Withheld, Section 40	30/09/2024	Fit new Battery	115655	Repairs	SKODA OCTAVIA ESTATE
00055489	Withheld, Section 40	01/10/2024	Supply Front Tyre Low Tread	116402	Tyres	SKODA OCTAVIA ESTATE