

<u>Job Number</u>	<u>Date In</u>	<u>Registration Number</u>	<u>Job Description</u>	<u>Latest Distance</u>	<u>Workshop Job Sheet Type</u>	<u>Vehicle Make Model Derivative</u>
00002620	01/05/2018	SECTION 40	The engine warning light has activated and a message has displayed saying "low engine power". When attempting to accelerate the engine appears 'flat' and the vehicle does not want to increase it's speed.	20094	Breakdown	VAUXHALL ASTRA HATCHBACK
00004371	15/08/2018	SECTION 40	DRIVERS SEAT BELT WILL FASTEN IN THE SEAT BELT CLIP..		Breakdown	VAUXHALL ASTRA HATCHBACK
00004821	12/09/2018	SECTION 40	Type 2 Light Vehicle Inspection-Type 2 Saftey Inspection. Oil & Filter. Fuel Filter.	25238	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
			Low Tread			
			Replace Front Brake Pad			
			Replace Rear Brake Pad			
			Replace Both Wiper Blade			
00007038	29/01/2019	SECTION 40	Driven and brakes not effective vehicle at Uttoxeter	34015	Breakdown	VAUXHALL ASTRA HATCHBACK
			Clutch			
			brake recall			
00009092	24/05/2019	SECTION 40	Type 3 light Vehicle Inspection-Type 3	39260	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
			front washers inop/blocked?			
			carry out road test			

00011146	24/09/2019	SECTION 40	Clutch	45705	Warranty Ext	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	--------	-------	--------------	--------------------------------

Warranty Repair Check

00011733	23/10/2019	SECTION 40	Clutch gone	45871	Warranty Ext	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	-------------	-------	--------------	--------------------------------

00015107	06/03/2020	SECTION 40	Type 1 Light Vehicle Inspection-Type 1	57198	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	--	-------	--------------------------	--------------------------------

00015108	06/03/2020	SECTION 40	MOT External Carried out	57198	M.O.T.	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	--------------------------	-------	--------	--------------------------------

00015194	11/03/2020	SECTION 40	Low Tread	50929	Tyres	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	-----------	-------	-------	--------------------------------

00022126	24/11/2020	SECTION 40	Type 3 light Vehicle Inspection-Type 3	64108	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	--	-------	--------------------------	--------------------------------

00022127	24/11/2020	SECTION 40	Fit new Cambelt Replacement	64108	Repairs	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	-----------------------------	-------	---------	--------------------------------

00022148	25/11/2020	SECTION 40	Check Brake Pads	64108	Repairs	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	------------------	-------	---------	--------------------------------

00022569	08/12/2020	SECTION 40	Check Fuel System - engine will not start and has diesel leak underneath	64108	Breakdown	VAUXHALL ASTRA HATCHBACK
00023651	12/01/2021	SECTION 40	Supply Front O/S 1 Tyre Punctured	65454	Tyres	VAUXHALL ASTRA HATCHBACK
00024811	25/02/2021	SECTION 40	MOT External	67619	M.O.T.	VAUXHALL ASTRA HATCHBACK
00028761	05/08/2021	SECTION 40	Type 1 Light Vehicle Inspection-Type 1	76332	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
			Interior Sanitisation-Carry out Interior Sanitisation			
00028937	16/08/2021	SECTION 40	Check & Adjust Front Washer Jets	76332	Repairs	VAUXHALL ASTRA HATCHBACK
			Fit new Front Wiper Blades			
			Renew Rear Light Bulb			
			Fit new Front Brake Discs and Pads			
			Fit new Rear Brake Discs and Pads			
			Fit new Rear Wiper Blades			
00031211	03/11/2021	SECTION 40	Supply Rear Tyre Damage	79363	Tyres	VAUXHALL ASTRA HATCHBACK

00035000	27/04/2022	SECTION 40	Check Clutch clutch pedal got stuck down	89003	Breakdown	VAUXHALL ASTRA HATCHBACK
00035257	09/05/2022	SECTION 40	Type 3 light Vehicle Inspection-Type 3	89969	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
00035258	09/05/2022	SECTION 40	Carry out Quality Control Check (MOT)	89969	M.O.T.	VAUXHALL ASTRA HATCHBACK
00035514	18/05/2022	SECTION 40	Fit new Front Shock Absorber Dust Covers	89969	Repairs	VAUXHALL ASTRA HATCHBACK
00035759	19/05/2022	SECTION 40	Supply Front N/S Tyre Low Tread	89969	Tyres	VAUXHALL ASTRA HATCHBACK
00036072	15/06/2022	SECTION 40	Check Clutch Unable to get into gear	91370	Breakdown	VAUXHALL ASTRA HATCHBACK
00039875	11/11/2022	SECTION 40	Supply Rear O/S 1 Tyre Low Tread	99503	Tyres	VAUXHALL ASTRA HATCHBACK
00040706	09/12/2022	SECTION 40	Supply N/S Light Bulb	100985		VAUXHALL ASTRA HATCHBACK

00040259	13/12/2022	SECTION 40	CLUTCH PEDAL STUCK DOWN - Clutch Pedal Clutch sticks down regularly whilst driving	100985	Repairs	VAUXHALL ASTRA HATCHBACK
00040417	19/12/2022	SECTION 40	Type 1 Light Vehicle Inspection-Type 1	100985	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
00040763	05/01/2023	SECTION 40	Fit new Front & Rear Brake Pads	100985	Repairs	VAUXHALL ASTRA HATCHBACK
00041505	11/01/2023	SECTION 40	Supply Light Bulb	102294		VAUXHALL ASTRA HATCHBACK
00043479	05/04/2023	SECTION 40	Supply Rear O/S 1 Tyre Punctured	106208	Tyres	VAUXHALL ASTRA HATCHBACK
00045273	21/06/2023	SECTION 40	Supply Rear O/S 1 Tyre Punctured	109806	Tyres	VAUXHALL ASTRA HATCHBACK
00044703	23/06/2023	SECTION 40	DOOR HINGE / HANDLE - Unable to open doors.Only the boot will open.	109883	Repairs	VAUXHALL ASTRA HATCHBACK
			Unable to open car doors. Only the boot will open			
00044821	29/06/2023	SECTION 40	Supply Rear O/S TPMS	109883	Tyres	VAUXHALL ASTRA HATCHBACK

00045936	24/08/2023	SECTION 40	CLUTCH PEDAL STUCK DOWN - Clutch intermittently gets stuck down and car will not be put into gear. Can be flicked back up with foot. Believe this has been reported previously but returned the same.	111884	Repairs	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	---	--------	---------	--------------------------------

00046150	05/09/2023	SECTION 40	Type 3 light Vehicle Inspection-Type 3	111884	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
			Carry out Quality Control Check (MOT)			
			Repair TPMS			
			Fit new Front Wiper Blades			
			Repair Front Washer Jets			
			Refit Front N/S Wheel Arch Liner			
			Fit new Front O/S Wheel			

00046452	18/09/2023	SECTION 40	Supply Front O/S Tyre Punctured	111884	Tyres	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	---------------------------------	--------	-------	--------------------------------

00050202	05/03/2024	SECTION 40	Check Clutch It appears that the clutch has gone.	118417	Repairs	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	---	--------	---------	--------------------------------

00050513	18/03/2024	SECTION 40	Fit new TPMS x2	118417	Repairs	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	-----------------	--------	---------	--------------------------------

00050525	18/03/2024	SECTION 40	Supply N/S 2 TPMS	118417	Tyres	VAUXHALL ASTRA HATCHBACK
----------	------------	------------	-------------------	--------	-------	--------------------------------

Supply TPMS
Supply Front N/S 1 Tyre Low Tread

00054933	30/09/2024	SECTION 40	Type 1 Light Vehicle Inspection - Type 1	125868	Scheduled Maintenance	VAUXHALL ASTRA HATCHBACK
			Fit new Front Brake Discs and Pads			